


PRODUCT DESCRIPTION

- » Fast, non-contact measurement
- » 2 point laser measurement spot marker
- » Display of min./max. values
- » MTM 5010 External temperature probe can be connected
- » Optimal for plastic parts

INCLUDED IN THE DELIVERY

- » Certificate of calibration and a battery (9V block)



Optics	Wt.	Emission level	Error limit	Scaling	MB ¹⁾	No.	#CU#
30 : 1	200 g	0,1 - 1	± 1 °C	0,1 °C	-30 - +400°C	MTM 1100/830-T4	XX,YY

1) MB: measuring range